EXHIBIT -B



NOTES:

1) ⬡ – DENOTES SUB ASSEMBLY

WEBER POINT
FABRIC ASSEMBLY
DWG. 1000 A