




Bored in Place Wall C Line "D" Line "E" SIM BETWEEN SHEAR WALLS  
 12" conc wall      24" conc wall




REVISIONS	DATE	BY
1. REVISION		
2. REVISION		
3. REVISION		
4. REVISION		
5. REVISION		
6. REVISION		
7. REVISION		
8. REVISION		
9. REVISION		
10. REVISION		
11. REVISION		
12. REVISION		
13. REVISION		
14. REVISION		
15. REVISION		
16. REVISION		
17. REVISION		
18. REVISION		
19. REVISION		
20. REVISION		
21. REVISION		
22. REVISION		
23. REVISION		
24. REVISION		
25. REVISION		
26. REVISION		
27. REVISION		
28. REVISION		
29. REVISION		
30. REVISION		
31. REVISION		
32. REVISION		
33. REVISION		
34. REVISION		
35. REVISION		
36. REVISION		
37. REVISION		
38. REVISION		
39. REVISION		
40. REVISION		
41. REVISION		
42. REVISION		
43. REVISION		
44. REVISION		
45. REVISION		
46. REVISION		
47. REVISION		
48. REVISION		
49. REVISION		
50. REVISION		
51. REVISION		
52. REVISION		
53. REVISION		
54. REVISION		
55. REVISION		
56. REVISION		
57. REVISION		
58. REVISION		
59. REVISION		
60. REVISION		
61. REVISION		
62. REVISION		
63. REVISION		
64. REVISION		
65. REVISION		
66. REVISION		
67. REVISION		
68. REVISION		
69. REVISION		
70. REVISION		
71. REVISION		
72. REVISION		
73. REVISION		
74. REVISION		
75. REVISION		
76. REVISION		
77. REVISION		
78. REVISION		
79. REVISION		
80. REVISION		
81. REVISION		
82. REVISION		
83. REVISION		
84. REVISION		
85. REVISION		
86. REVISION		
87. REVISION		
88. REVISION		
89. REVISION		
90. REVISION		
91. REVISION		
92. REVISION		
93. REVISION		
94. REVISION		
95. REVISION		
96. REVISION		
97. REVISION		
98. REVISION		
99. REVISION		
100. REVISION		



03210-04  
 2-8-00  
 RHT





SHT. CONTENT		
P.I.P. WALLS		
STRUCTURE		
ESSENTIAL SERVICES		
CONTRACTOR		
TURNER		
TAD COLOR	JOB NO. 451	SHEET NO. P.1
MADE AT DOW	DATE 1/25/00	SHT. OF SHT.



218.00  
MK



03210-04  
2-5-00  
RHT



SHT. CONTENT		
COLUMN PLAN		
STRUCTURE		
ESSENTIAL SERVICES GARAGE		
CONTRACTOR		
TURNER		
TIM COLOR	JOB NO. 45	SHEET NO. C-1
MADE BY DON	DATE 1/12/00	SHT. OF 5HT








































USE 3/4" A  
 20x143-0 Δ 5/8  
 ORANGE  
 USE 3/4" A  
 20x143-0 Δ 5/8  
 GREY  
 USE 3/4" A  
 20x143-0 Δ 5/8  
 YELLOW

14 ADDED 55-0 Δ 1/2 WHITE  
 20x143-0 Δ 5/8 IN COLOR  
 USE 3/4" A  
 20x143-0 Δ 5/8

TYP. JACKING FORCE IS  
 95% UN.0

SPACING	1	2	3	4	5	6
17'-0"	17'-0"	17'-0"	17'-0"	17'-0"	17'-0"	17'-0"
6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"
6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"
6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"
6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"
6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"	6'-0"

REVISIONS	BY

**ALVARADO**  
 CIVIL ENGINEERING INC.

SUB FLOOR  
 GARAGE  
 STRENGTH





ESSENTIAL SERVICES  
 PARKING GARAGE  
 SECTION

Date 4.4.2002  
 Scale 1/8" = 1'-0"  
 Draw 15  
 Job 451  
 Sheet  
 PT-5  
 Of 5









Approved  
 Approved as corrected  
 Review and Resubmit  
 Rejected

Fabrication / installation may be authorized. Approval does not authorize changes to the Contract Sum or Contract time.  
 Fabrication / installation MAY NOT be undertaken in resubmitting, limit corrections to items marked.

Review is only for general conformance with the design concept in the contract documents. Any action shown is subject to the requirements of the plans and specifications. Contractor is responsible for dimensions which shall be confirmed and corrected at the job site. Fabrication processes and techniques of construction, coordination of his work with that of all other trades, and satisfactory performance of his work.  
 Review / approval neither extends nor alters any contractual obligations of the Architect or Contractor.

ENGLISH HARPER RETA  
 By: *BH* Date: *5/3/00*

**RECEIVED**  
 APR 25 2000  
 TURNER CONSTRUCTION

*Coordinate Curbs at stud wall locations*  
*Referred to Struct. review*

Checking is only for general conformance with the design concept of the project and general conformance with the information given in the contract documents. Any action shown is subject to the requirements of the plans and specifications. Contractor is responsible for dimensions which shall be confirmed and corrected at the job site. Fabrication processes and techniques of construction, coordination of his work with that of all other trades and the satisfaction per formance of his work.

Dealer to review and be in agreement with Contractor to appropriate engineer prior to proceeding with fabrication, in event of discrepancy contact owner's representative.

REINFORCING & BRIDGE ASSOCIATES, STRUCTURAL ENG. INC.  
 1325 G ST. SUITE 100  
 SACRAMENTO, CALIFORNIA 95811





DATE: *5-1-00*  
 BY: *PR*



SHT. CONTENT		
D TO D.4		
SLAB EDGES & L.W.D. 1Y+2Y + 15Y + 16Y		
STRUCTURE		
PARKING GARAGE		
CONTRACTOR		
TURNER		
TAG COLOR	JOB NO. 451	SHEET NO. 51
MADE BY <i>Don</i>	DATE <i>9/20/00</i>	SHT. OF <i>5</i> SHTS.







Approved  
 Approved as corrected  
 Deleted and Resubmitted  
 Retained

Fabrication / installation may not underlain. Approval does not authorize changes to the Contract Sum or Contract time.  
 Fabrication / installation MAY NOT be undertaken in residential and corrections to items marked.

Review is only for general conformance with the design shown in the contract documents. Any action shown is subject to the requirements of the plans and specifications. Contractor is responsible for dimensions, fabrication processes and techniques of construction, coordination of the work with that of other trades, and satisfactory performance of his work.  
 Engineer's approval neither endorses nor assumes any contractual obligations of the Architect or Contractor.

ENGLISH HARPER RETA  
 By *BH* Date 5/3/00

*Coordinate curbs at stud wall locations*

*Deferred to Struct review.*






RECEIVED  
 APR 20 2000  
 THE UNIVERSITY OF CALIFORNIA

6652D  
 0310-15  
 4-27-00

**ALAMILLO**  
 STEEL  
 207 EAST CHANNEL ROAD  
 BENICIA, CALIFORNIA 94510-1193

SHT. CONTENT		
D T B A		
SLAB EDGE & L.W.D. 1Y+2Y + 157 to 167		
STRUCTURE		
PARKING GARAGE		
CONTRACTOR		
TURNER		
TAB. COLOR	JOB NO. 451	SHEET NO. 51
MADE BY DON	DATE 4/20/00	SHT. OF 51





Approved  
 Approved as corrected  
 Review and Resubmit  
 Rejected

Fabrication / Installation may be undertaken if approval does not authorize charges to the Contract Sum or Contract Time.  
 Fabricator's Installation MAY NOT be undertaken in reworking items corrections to items marked.

Review is only for general conformance with the design concept in the contract documents. Any action shown is subject to the requirements of the plans and specifications. Contractor is responsible for dimensions and quantities of work which shall be confirmed and completed at the job site. Fabrication processes and techniques of construction, satisfactory performance of the work.  
 Review / approved initials express nor alters any contractual obligations of the Architect or Contractor.

ENGLISH HARPER RETA  
 Reviewer for General Acceptance Only. This review does not relieve the subcontractor of the responsibility for making accurate and accurate fit with the work of other trades.

TURNER CONSTRUCTION  
 JOB 66825  
 SUBMITTAL # 03210-13  
 DATE 4-22-00 BY *DL*

Coordinate  
 Curb at stud  
 wall locations

**RECEIVED**  
 APR 25 2000  
 TURNER CONSTRUCTION

Deferring to  
 Struct. review.

(Checking is only for general conformance with the design concept of the project and general compliance with the information given in the contract documents. Any action shown is subject to the requirements of the plans and specifications. Contractor is responsible for dimensions and quantities of work which shall be confirmed and completed at the job site. Fabrication processes and techniques of construction, satisfactory performance of the work.  
 Designer to review and be in agreement with comments by structural engineer prior to proceeding with fabrication. In event of disagreement, contact Designer's representative.  
 DESIGNER & ENGINEER ASSOCIATES, STRUCTURAL, INC. 1800 FALCON BLVD., SUITE 1155 COLUMBIA, SC 29204-1055

REVISIONS:  
 NO. DATE BY  
 1 5.1.00 DL  
 2 5.1.00 DL



SHT. CONTENT		
D T 15.4		
SLAB EDGE & L.W. D-4 1Y+2Y + 15Y to 6Y		
STRUCTURE		
PARKING GARAGE		
CONTRACTOR		
TURNER		
TAG COLOR	JOB NO. 451	SHEET NO. 51
MADE BY DL	DATE 4/20/00	SHT. OF SHTS.



















